


# Polymak®

## PM-127PBS

## PORTABLE BAND SAW


|                |              |
|----------------|--------------|
| Frequency:     | 50Hz/60Hz    |
| Voltage:       | 220V         |
| Power:         | 1100W        |
| No Load Speed: | 0.7-2.4m/s   |
| Saw blade      | 1141×13×0.65 |



# Polymak®

## PM-127PBS SPARE PARTS LIST

| No | Parts Name        | Pcs | Seri No | INR | No | Parts Name           | Pcs | Seri No | INR |
|----|-------------------|-----|---------|-----|----|----------------------|-----|---------|-----|
| 1  | Sub handle        | 1   |         |     | 41 | Bear                 | 1   |         |     |
| 2  | Screw             | 1   |         |     | 42 | Class II gear        | 1   |         |     |
| 3  | Anti-loose        | 4   |         |     | 43 | Gear box             | 1   |         |     |
| 4  | Handle base       | 1   |         |     | 44 | Gear box cover       | 1   |         |     |
| 5  | Screw             | 1   |         |     | 45 | Screw M8×14          | 2   |         |     |
| 6  | Light back cover  | 1   |         |     | 46 | Holder               | 1   |         |     |
| 7  | LED light         | 1   |         |     | 47 | Slide block          | 1   |         |     |
| 8  | LED Cover         | 1   |         |     | 48 | Class III gear shaft | 1   |         |     |
| 9  | Light base        | 1   |         |     | 49 | Gear box cover       | 1   |         |     |
| 10 | Screw             | 6   |         |     | 50 | Drive plate R2101    | 1   |         |     |
| 11 | Left handle       | 1   |         |     | 51 | Non-slip band        | 2   |         |     |
| 12 | Speed controller  | 1   |         |     | 52 | Copper bush          | 1   |         |     |
| 13 | Switch            | 1   |         |     | 53 | Press plate          | 1   |         |     |
| 14 | Right handle      | 1   |         |     | 54 | Screw M8×14          | 4   |         |     |
| 15 | Sleeve            | 1   |         |     | 55 | Movable support      | 1   |         |     |
| 16 | Cable             | 1   |         |     | 56 | Locating sleeve      | 4   |         |     |
| 17 | Cable plate       | 1   |         |     | 57 | Dust-proof washer    | 2   |         |     |
| 18 | Screw             | 9   |         |     | 58 | Drive plate R2101    | 1   |         |     |
| 19 | Screw             | 10  |         |     | 59 | Circlip Φ16          | 1   |         |     |
| 20 | adjustable wrench | 1   |         |     | 60 | Drive plate cover    | 2   |         |     |
| 21 | Adjusting shaft   | 1   |         |     | 61 | Blade holder         | 1   |         |     |
| 22 | Screw             | 4   |         |     | 62 | Brush                | 1   |         |     |
| 23 | screw             | 16  |         |     | 63 | Screw M5×25          | 4   |         |     |
| 24 | round pin         | 3   |         |     | 64 | Locating block II    | 1   |         |     |
| 25 | screw             | 10  |         |     | 65 | Locating block I     | 1   |         |     |
| 26 | support sleeve    | 1   |         |     | 66 | 624 Bearing          | 3   |         |     |
| 27 | support           | 1   |         |     | 67 | Pin 4×16             | 4   |         |     |
| 28 | brush cap         | 2   |         |     | 68 | 696 Bearing          | 8   |         |     |
| 29 | brush holder      | 2   |         |     | 69 | Screw M5             | 4   |         |     |
| 30 | carbon brush      | 2   |         |     | 70 | Screw M4×8           | 2   |         |     |
| 31 | housing           | 1   |         |     | 71 | Screw M5×14          | 6   |         |     |
| 32 | stator sleeve     | 1   |         |     | 72 | O ring               | 1   |         |     |
| 33 | Tension spring    | 2   |         |     | 73 | Screw M6×40          | 4   |         |     |
| 34 | stator            | 1   |         |     | 74 | Locating sleeve      | 1   |         |     |
| 35 | screw             | 2   |         |     | 75 | Wrench S4            | 1   |         |     |
| 36 | anti-wind ring    | 1   |         |     | 76 | Wrench S5            | 1   |         |     |
| 37 | bearing sleeve    | 1   |         |     | 77 | Blade 1140×13×0.65   | 1   |         |     |
| 38 | rotor             | 1   |         |     |    |                      |     |         |     |
| 39 | Middle cover      | 1   |         |     |    |                      |     |         |     |
| 40 | Screw             | 3   |         |     |    |                      |     |         |     |



| No | Parts Name     | Pcs | Seri No | INR | No | Parts Name    | Pcs | Seri No | INR |
|----|----------------|-----|---------|-----|----|---------------|-----|---------|-----|
| 1  | Lever pin      | 1   |         |     | 21 | Big plate     | 1   |         |     |
| 2  | Lever seat     | 1   |         |     | 22 | little plate  | 1   |         |     |
| 3  | Lever          | 1   |         |     | 23 | Buffer block  | 1   |         |     |
| 4  | prep           | 1   |         |     | 24 | Locking block | 1   |         |     |
| 5  | Screw rod      | 1   |         |     | 25 | screw         | 1   |         |     |
| 6  | nut            | 1   |         |     | 26 | Spring washer | 4   |         |     |
| 7  | Retaining ring | 1   |         |     | 27 | Flat washer   | 4   |         |     |
| 8  | Movable jaw    | 1   |         |     | 28 | screw M8×15   | 4   |         |     |
| 9  | pin            | 1   |         |     | 29 | Flat washer   | 1   |         |     |
| 10 | cotter pin     | 1   |         |     | 30 | Screw M8×10   | 2   |         |     |
| 11 | pad            | 2   |         |     | 31 | Screw M4×12   | 18  |         |     |
| 12 | Screw support  | 1   |         |     | 32 | Screw M8×25   | 1   |         |     |
| 13 | pin 6×30       | 1   |         |     | 33 | Screw M4×10   | 1   |         |     |
| 14 | Retaining ring | 4   |         |     | 34 | Spanner S8    | 4   |         |     |
| 15 | Wheel pin      | 2   |         |     |    |               |     |         |     |
| 16 | wheel          | 2   |         |     |    |               |     |         |     |
| 17 | Torsion spring | 1   |         |     |    |               |     |         |     |
| 18 | Base           | 1   |         |     |    |               |     |         |     |
| 19 | Screw          | 1   |         |     |    |               |     |         |     |
| 20 | Screw          | 1   |         |     |    |               |     |         |     |